## Example 26

## Conditions

A workpiece was stood up and then lifted using horizontal lifting clamps on one side. After the workpiece was stood up straight, the clamps came off, and it turned over and fell.

