


Example 18

Conditions

To turn over a piece of H-shape steel, the lifting shackle of the clamp was attached upside down and inserted. Because the insertion was insufficient, when the beam was lifted, the clamp came off.

Results


Models: VAR(VARE)



Similar applicable models

G(GE), VA(VAE),
and AMS


⚠ WARNING



● Observe proper procedures.

Less than 5 mm

- Insert completely.
- Be sure to stay clear of the swinging range of objects being lifted.



● Always use 2-point lifting.