

## Example 4 1

## Conditions



When a thickly-coated steel product was lifted using two vertical lifting clamps, the paint slipped off and the object being lifted fell.

Model : E

## Results


### Similar applicable models

SL(SLE),RS(RSE),  
SLT(SLTE), and  
RST(RSTE)



## WARNING

- Before lifting coated steel products, be sure to replace the swivel jaws and cams with new ones.



Cam



Swivel jaw

- Do not use clamps on steel products that have a coating 0.2 mm or more thick on each side.



The object slips.

The object is not gripped sufficiently tightly.



**PROHIBITED ACTION**

Coating is too thick.