



Example 21

Conditions

When a beam was being moved, using 2-point lifting, it came into contact with some other material. This unbalanced the load and it fell.

Results


Models: VAR(VARE)



Similar applicable models

G(GE), VA(VAE),
and AMS

⚠WARNING



- Do not allow clamps or objects being lifted to come in contact with anything when being transported.



- Be sure to stay clear of the swinging range of objects being lifted.

