

Example 14

Conditions


Vertical lifting was performed with lateral lifting clamps, and two steel plates were lifted from a single hook.

Results


Models: VAR (VARE)

Similar applicable models

G (GE), VA (VAE),
and AMS



⚠ WARNING



- Observe proper operating procedures.
- Use the right clamps.
- Use two vertical lifting clamps to lift one steel plate.