Example 29

Conditions

A steel plate was being transported using a universal screw-type clamp whose swivel jaw was missing. It slipped out of the clamp and fell.

